

# Test Report Number:150728004SHF-BP-1

Applicant Name: Taizhou Huali Plastic Co. Ltd. Original Report Date: August 5, 2015

Applicant Address: Zhangdian Industrial Zone, Jiangyan,

Jiangsu Prov., P. R. China

Attn: Philip Yuan

## Sample Description:

Product: Wood-Plastic Composite Flooring (VINYL FLOORING + WPC BOARD)

Model: /

Samples Quantity: 1 piece

Sample ID: S150728004SHF-001 Date Received: 2015-07-28

Date Test Conducted: 2015-07-28~2015-08-05

### **Tests Conducted:**

Test Methods: With reference to EN 14372:2004, by Gas Chromatography-Mass Spectrometry (GC-MS) analysis.

### **Conclusion:**

For details refer to attached page(s).

The conclusions of this test report may not be used as part of the requirements for Intertek product certification. Authority to Mark must be issued for a product to become certified.

Should you have any gueries about the test report, please contact:

Approved by: Checked by: Prepared by:

Sun Sun Sally Xie Evyn Cui

Assistant Manager Technical Supervisor Assistant Engineer

Report Template Revision Date: 1st January 2015

Page 1 of 3



# **Test Report**

Report Number:150728004SHF-BP-1

## Test Items, Method and Results:

Test items: Phthalate content test

Test Method: With reference to EN 14372:2004, by Gas Chromatography-Mass Spectrometry (GC-MS) analysis.

Tested compound	Result (%, w/w)	Limit (%,w/w)
		(MAX.)
Di-butyl phthalate (DBP)	ND	
Di(2-ethyl hexyl) phthalate(DEHP)	ND	
Benzyl butyl phthalate (BBP)	ND	
Sum of three phthalates	ND	0.1
Di-iso-nonyl phthalate (DINP)	ND	
Di-n-octyl phthalate (DNOP)	ND	
Di-iso-decyl phthalate (DIDP)	ND	
Sum of three phthalates	ND	0.1

#### Note:

- 1. The above limit was quoted according to Annex XVII items 51 & 52 of the REACH regulation (EC) NO.1907/2006 & Amendment NO.552/2009 for phthalate content in toys and children care articles.
- 2. Detection limit = 0.01% (w/w)
- 3. ND = Not detected

Intertek Testing Services Ltd., Shanghai
No.7 Building, No. 6958 Daye Road, Fengxian District, Shanghai

Tel: 021-61136116 Fax: 021-61189921 Website: <u>www.intertek.com</u>

Report Template Revision Date: 1st January 2015



# Test Report

Report Number: 150728004SHF-BP-1

## Appendix A: Sample photos




Fig.1~2 Sample as received

The End of Report

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Intertek Testing Services Ltd., Shanghai
No.7 Building, No. 6958 Daye Road, Fengxian District, Shanghai
Tel: 021-61136116 Fax: 021-61189921 Webs

Tel: 021-61136116 Fax: 021-61189921 Website: <u>www.intertek.com</u>

Report Template Revision Date: 1st January 2015